




**DEFECTS ASSOCIATED WITH LOCOMOTIVE BOILERS.  
BROKEN FIREBOX STAYS**






Fig. 40. Screw Stay-Bolt.




Figure 1




Figure 3

Stays with "Tell-Tale" Hole





